








**NOTE:**  
UNLESS NOTED OTHERWISE ALL  
CIRCUIT BREAKERS ARE TO BE SET AT

- lo 100%
- lr 1
- lsd 6

**NOTE:**  
UNLESS NOTED OTHERWISE ALL  
CIRCUIT BREAKERS ARE TO BE SET AT

- lo 100%
- Ir 1
- Isd 6

**LEGEND:**

- |   |                                      |
|---|--------------------------------------|
|  | NON-AUTO SWITCH LOAD BREAK ISOLATOR. |
|  | CIRCUIT BREAKER.                     |
|  | FUSE.                                |
|  | MECHANICAL INTERLOCK.                |
|  | MANUAL TRANSFER SWITCH.              |
|  | QECM V4 CT RETAIL METER.             |
|  | THREE PHASE.                         |